
## Waitrose

### Wokingham Snacking Cabinets



# Cabinets are located in branch entrance area & fail to maintain correct temperatures.

Cabinets in question are 'Kingston' manufactured by Verco Ltd. These are standard chillers found throughout the Waitrose estate. Later models (as per this branch) are operating on hydrocarbon refrigerant

Air disturbance created by door openings & H&V vents in the surrounding area is believed to be cause of the poor cabinet performance.


To overcome this issue RJM have fitted double glazed frameless doors to both cabinets. The following pages show the features & benefits of the new door system





Frameless double glazed acrylic door system maintains full vision into the cabinet & hence does not detract from merchandising impact.

Double glazed panels eliminate condensation in higher humidity conditions. Acrylic construction prevents 'glass shattering' potential



Retrofit to existing cases is a simple process. Hinge areas are easy to clean and require minimal maintenance.





Original Cabinet
Includes traditional
tube lighting &
nightblind.



Modifications include removal of standard canopy lamps & introduction of integrated LED lighting strips. A hydrocarbon safety system has also been fitted.

**Modified Cabinet**Light tube &
nightblind
removed.







Integrated door handle, no protrusions or dirt traps.

Doors hinge through 160° for easy product replenishment. Avoids door clashes in narrow aisles.


Frameless design gives full vision into display area. Lightweight construction makes it possible to fit to cases.

many types of





#### System 902 (°C)



### Performance improvement.



Waitrose

Wokingham

Verco Snacking Chillers

RJM door solution



